Supplement


Title:	712 Inst.Sht.	Supplement Issue:	6
Part Number:	650280	Issue Date:	2/11
Print Date:	August 1997	Page Count:	5
Revision/Date	: 2, 5/04		

This supplement contains information necessary to ensure the accuracy of the document described above.



Change #1, 47807

Under *Getting Acquainted with the Calibrator*, replace the figure with the following:



Under **Display Elements**, add the following to the table:

(9) Span Check Step and Ramp	Lit when in Span Check, step
	and ramp modes

Prior to *Simulating an RTD*, add the following sections:

Auto Shut-Off (Power Saver)

The Calibrator automatically turns off after 30 minutes of inactivity. To reduce the time or disable this feature:

- With the Calibrator OFF, press
 P.S.xx is displayed, where xx is the turn-off time in minutes. OFF means the power saver is disabled.
- 2. Press ▲ and/or ▼ to increase or decrease the turn off time in minutes.

Supplement

Span Check

The calibrator allows you to store 0% and 100% setpoints for each output type. Once setpoints are stored, the span check feature allows you to quickly toggle back and forth from 0% to 100% or to step in 25% increments.

Automatic step and ramp modes can be enabled while in span check mode by simultaneously pressing or . First select the desired output range, then proceed to store the setpoints:

- 1. Use ▲ and ▼ to set the output to the desired value for 0%.
- Press ▲ and ▲ simultaneously to store the 0% value.
- 3. Use ▲ and ▼ to set the output to the desired value for 100%.
- 4. Press ▲ and ▲ simultaneously to store the 100% value.

Under **Testing and Replacing the Fuses**, delete the entire section and the corresponding figure.

Under *Replacement Parts and Accessories*, delete the F1, F2 row and under MP86 change the part number,

From: 620168 To: 2397526

Remove the F1 and F2 fuses from the replacement parts illustration.

Under **Specifications**, replace the **Ohms Specifications** table with the following two tables:

712 Instruction Sheet

	Accuracy *				
Ohms Range	4-Wire	2- and 3-wire			
0 to 400 Ω 400 to 3200 Ω	$\begin{array}{c} 0.025 \ \% \pm 0.05 \ \Omega \\ 0.025 \ \% \pm 0.05 \ \Omega \end{array}$	$\begin{array}{c} 0.025 \ \% \pm 0.1 \Omega \\ 0.025 \ \% \pm 0.55 \ \Omega \end{array}$			
Excitation current : 0.2 mA					
Maxiumum input voltage: 30 V *2-wire: Does not include lead resistance 3-wire: Assumes matched leads					

Ohms Source Specifications

Ohms Range	Excitation Current from Measurement Device	Accuracy
0 to 400 Ω 0 to 400 Ω 400 to 1500 Ω 1500 to 3200 Ω	0.1 to 0.5 mA 0.5 to 3.0 mA 0.05 to 0.8 mA 0.05 to 0.4 mA	$\begin{array}{l} 0.025\% \pm 0.1 \ \Omega \\ 0.025\% \pm 0.05 \ \Omega \\ 0.025\% \pm 0.5 \ \Omega \\ 0.025\% \pm 0.5 \ \Omega \end{array}$

Under *RTD Specification*, replace the table with the following:

	Range °C	Accuracy °C *				
RTD		Measure			Allowable Excitation	
Туре		4-wire	2- and 3-wire	Source	mA	
Ni120	-80.0 to 260.0	0.20	0.25	0.2	0.1 to 3.0	
Pt100 385	-200.0 to 100.0	0.20	0.28	0.2	0.1 to 3.0	

Supplement

712 Instruction Sheet

	1		1		
	100.0 to 300.0	0.30	0.40	0.3	
	300.0 to 600.0	0.40	0.52	0.4	
	600.0 to 800.0	0.50	0.65	0.5	
Pt200 385	-200.0 to 100.0	0.80	1.00	0.8	0.05 to 0.8
	100.0 to 300.0	0.90	1.15	0.9	
	300.0 to 630.0	1.00	1.20	1.0	
Pt500 385	-200.0 to 100.0	0.40	0.60	0.4	0.05 to 0.8
	100.0 to 300.0	0.50	0.75	0.5	
	300.0 to 630.0	0.60	0.90	0.6	
Pt1000 385	-200.0 to 100.0	0.20	0.25	0.2	0.05 to 0.4
	100.0 to 300.0	0.30	0.40	0.3	
	300.0 to 630.0	0.40	0.52	0.4	
Pt100 3926	-200.0 to 100.0	0.20	0.28	0.2	0.1 to 3.0
	100.0 to 300.0	0.30	0.40	0.3	
	300.0 to 630.0	0.40	0.52	0.4	

712 Instruction Sheet

Supplement

Pt100 3916	-200.0 to 100.0	0.20	0.28	0.2	0.1 to 3.0
	100.0 to 300.0	0.30	0.40	0.3	
	300.0 to 630.0	0.40	0.52	0.4	

Addresses pulsed transmitters and PLC's with pulses as short as 5ms.

Excitation current from 712: 0.2mA

Maximum input voltage: 30V

*2-wire: Does not include lead resistance

3-wire: Assumes matched leads

Change #2

Under General Specifications, add the following:

Protection Class: Pollution Degree II

Change #3

On the second panel, under **International Symbols**, add the following:



Conforms to relative Australian standards.

Change #4

In the Replacement Parts and Accessories table,

Change:

Test lead, red	688051	2
Test lead, black	688066	2

To:

3397308	2
	3397308