

I OO,OOO-count Graphical Multimeters MTX 328 I MTX 3282 MTX 3283



Contents

General Instructions	3
Introduction	3
Symbols used on the instrument	3
Precautions and safety measures	3
Safety features	4
Maintenance, metrological verification	4
Warranty	4
Cleaning	4
Measurement input protection systems	5
Special functions	5
Description of the instrument	6
Eront keyboarde (illustration)	0
Post (illustration marking)	۰۰۰۰۰ ۵
Measurement terminal block (illustration markings)	۰۰۰۰۰ ۵
measurement terminal block (inustration, markings)	0
Front (description)	6
inputs Discolar	9
	9
Functional description	10
Preparation for use	10
Initial settings	14
Specific configurations of the instrument	15
Initialisation of the values	16
Access to main functions	17
Range management	18
Display HOLD management HOLD, REL, SURV, SPEC, MEM	18
Access to secondary functions	25
MATH Function	27
Favourite function	29
SX-DMM Software kit (option)	31
Bluetooth (on –BT version)	31
Technical specifications	33
Voltage measurement	33
Current measurement	35
Erequency measurement	36
Resistance measurement	37
Continuity mode	37
Test diode	37
Canacitance measurement	38
Temperature measurement with Pt100 or Pt1000 sensor (MTX 3282, MTX 3283)	38
Temperature measurement with Lor K thermocounte	38
dBm measurement	38
Desitive or negative neak measurement	30
Resistive of negative peak measurement	39
Duty ratio DC+ DC-	30
Pulse counting CNT+ CNT-	
Clock	
Influences	40 //
Multimotor traccability, calibration	40
	40
General specifications	41
Environmental conditions	41
Power	41
Display	41
Safety	42
CEM	42
RS232 DB9F and USB optical cables (options)	42
Mechanical characteristics	
Box	
Packaging	42
Sumply accessories	40
Supply, accessories	43

General instructions

Introduction	

You have just acquired a 100,000-count graphical multimeter.

Thank you for your trust in our products.

It complies with safety standard EN 61010-1, double insulation, relative to electronic measuring instruments.

For optimum service, read this manual carefully and comply with the operating precautions.

Symbols used on the instrument

Warning: Risk of danger.

 Δ Refer to the operating manual to find out the nature of the potential hazards and the action necessary to avoid such hazards.



Equipment protected throughout by double insulation.



The rubbish bin with a line through it means that in the European Union, the product must undergo selective disposal for the recycling of electric and electronic material, in compliance with Directive WEEE 2002/96/EC.

2 Attention : Risk of electrical shock

Precautions and safety measures

- Read carefully all the notes preceded by the symbol \triangle .
- If you use this instrument in a way which is not specified, the protection which it provides may be compromised, putting you in danger.
- The safety of any system incorporating this instrument is the responsibility of the system assembler.
- This instrument has been designed for use indoors:
 - in an environment with pollution level 2,
 - at an altitude of less than 2000 m,
 - at a temperature between 0° C and 55° C
 - with relative humidity of less than 80% up to 31 $^{\circ}$ C.



- Measurement category III for voltages no higher than 1000 V (AC or DC) in relation to the earth.
- Measurement category IV for voltages no higher than 600 V (AC or DC) in relation to the earth.

Definition of measurement categories <u>CAT III</u>: Measurement category III corresponds to measurements on building installations.

Example: measurements on distribution panels, cabling, etc.

<u>CAT IV</u>: Measurement category IV corresponds to measurements taken at the source of low-voltage installations <u>Example</u>: metering and measurements on overvoltage protection devices...

before use

- Comply with environmental and storage conditions.
- For your safety, only use the leads delivered with the instrument: they comply with the norm EN 61010-031.
- The mounted probes must have an assigned measurement category III or IV and a rated voltage rated at least equal to the voltage of the circuit to be measured.
- Before using it, systematically check that it is in perfect condition.
- *during use* Never exceed the protection limit values indicated in the specifications for each type of measurement.
 - Before changing the function, disconnect the measurement leads from the circuit measured.
 - Never measure resistances on a live circuit.
 - When the instrument is connected to the measurement circuits, never touch an unused terminal.

General instructions (cont'd)

Safety features

- It is impossible to access the battery or fuse compartment without first disconnecting the measurement leads.
- When measuring voltages greater than 60 VDC or 30 VAC, the A symbol flashes on the display.
- Automatic detection of a connection on the "Ampere" terminal.
- When there is a persistent range overrun, an intermittent buzzer indicates the risk of electric shock.

Maintenance and metrological verification

Any access to the internal circuits for adjustment, servicing or repair of the unit *under power* must be undertaken only by qualified personnel, after reading the instructions in this manual.



A **qualified person** is a person who is familiar with the installation, its construction, its use and the hazards that exist. They are authorized to activate and deactivate the installation and equipment, in compliance with the safety instructions.

For all repairs under or outside of the warranty, return the device to your retailer.

Warranty



This equipment is guaranteed for **3 years** against any defect in materials or workmanship, in accordance with the general terms and conditions of sale, .

During this period, the equipment can only be repaired by the manufacturer. The manufacturer reserves the right to carry out repair or replacement of all or part of the equipment.

If the equipment is returned to the manufacturer, initial transport costs shall be borne by the customer.

The warranty does not apply in the event of:

- unsuitable use of the equipment or use with other incompatible equipment
- modification of the equipment without explicit authorization from the manufacturer's technical services
- repair carried out by a person not certified by the manufacturer
- adaptation to a specific application, not provided for in the definition of the equipment or by the operating manual
- an impact, a fall or flooding.

Unpacking - repacking



All the equipment was verified mechanically and electrically before shipping.

When you receive it, carry out a quick check to detect any damage that may have occurred during transport. If necessary, contact our sales department immediately and register any legal reservations with the carrier.

In the event of reshipping, it is preferable to use the original package. Indicate the reasons for the return as clearly as possible in a note attached to the equipment.

Cleaning

- Lef
- Turn the instrument off.
- Clean it with a damp cloth and soap.
- Never use abrasive products or solvents.
- Allow to dry before any further use.

General instructions (cont'd)

Measurement input protection systems



These multimeters are equipped with several protection systems:

- Varistor protection clips any transient overvoltages on the measurement terminals.
- PTC (positive temperature coefficient) protection protects against permanent overvoltages less than or equal to 1000 V during capacitance or resistance measurements and diode tests. This protection is reset automatically after the overload.
- A fuse (11 A) provides protection during intensity measurements.

Special functions

Automatic current measurement detection

- The number of input terminals is limited to 3: V, COM, A. Connection of the lead to the "Ampere" terminal automatically selects the corresponding function.
- When a function modification by the control keyboard is incompatible with the lead connection, it triggers a buzzer and a visual alarm (LEADS).

The current measurement is performed using autorange over the whole range.

Auto power-off



If the function is validated in the Sleep menu: the instrument shuts down automatically after 30 minutes if no action has occurred on the front panel during that time.

The instrument can be powered up again by pressing the key.

Automatic power-off is inhibited in:

- Surveillance mode (SURV)
- Memorize mode (MEM)
- Communication mode 💽 (optical link RS232C, USB, Bluetooth)
- when the value measured (Voltage or Current) on the multimeter's inputs exceeds the danger level.

Alert signal

An intermittent buzzer sounds:



- on the "Voltage" position, when the range is exceeded (MANUal and AUTO mode - last range)
- on the "Current" position, when the range is exceeded (**MANU**al) mode, when 10 Amperes or more is measured
- if the position of the leads and the function selected are incompatible
- when the danger thresholds are exceeded (function activated)

When the range is exceeded, the buzzer is accompanied by display of "O. L".

Danger threshold

When this symbol is activated:

- A
- the voltage on the "Volt" input exceeds 60 VDC or 30 VAC
- the current injected between the "Ampere" and COM exceeds 10 A
- the range is exceeded (voltage or current) in MANual mode

Description of the instrument



Description of the instrument (cont'd)

Front (description)

1 power on/off key

- Starting the multimeter.
- Stopping the multimeter.
- If there is a multimeter malfunction, a long press (> 1 s) on this key can be used to return to normal operation.

8 keys for selecting the main functions

Voltage measurement or access to the measurement type: AC, DC or AC+DC

- Selection using this key or the LU keys.
- Validation using the W key or after 2 s.



- Current measurement or access to the measurement type: AC, DC or AC+DC
- Selection using this key or the **U** keys.
- Validation using the W key or after 2 s.



Measurement of Frequency (Hz) on a VAC voltage or access to the manual frequency range < 900 kHz (default) or > 900 kHz.

A long press opens the menu for changing the voltage range.

- Selection using the **U** keys.
- Validation using the V or Validation using the Validation
- Voltage range quick change using the ways.

The selected range is recalled in the help line (i), see page 9.



Measurement of Resistance (Ohm)

By pressing again:

- Access to the **Continuity** test (♪)
- Access to Diode test (→)
- ∖ °C

Measurement of **Temperature** or access to the types of temperature measurements: $^{\circ}$ C, $^{\circ}$ F or K.

- Selection using the WIII keys.
- Validation using the W key or after 2 s.
- By pressing this key during measurement type selection, you can access the sensor type:
 - platinum probes: Pt 100, Pt 1000 only on MTX 3282 and MTX 3283
 thermocouples: J (TC J), K (TC K)
- Selection using the **W** keys.
- Validation using the W key or after 2 s.

The selected scale is recalled in the help line (i), see page 9.



Measurement of Capacitance

"Favourite" measurement configurable by the user.

A long press opens the "favourite" function configuration menu.

For the menu's configuration, see §. © Function.

Description of the instrument (cont'd)



Instrument Configuration menu.

This key can also be used to exit from a menu or submenu after validating it.

3 keys for navigation and modification of the menus

- Selection of a menu or function (up/down navigation).
- Increase or decrease of the variable selected.



- Selection of a **function** (left/right navigation).
- Modification of a function.
- Movement within sub-menus.

6 keys for activating the instrument's various modes

Range

Selection of the operating mode:

AUTO, AUTO PEAK (MTX 3282, MTX 3283), MANU.

- Selection using this key or the **U** keys.
 - Validation using the way or after 2 s.

If the measurement is single range, the range defined is forced and there is no effect if this key is pressed.

By pressing one of the WW keys, you can switch directly to **MANU**al mode and then modify the range.



Activation, deactivation of the **REL** (relative) mode. When it is active, a long press opens a window for setting the reference.



Activation, deactivation of the display of the **specifications** for the function and range selected.

Hold

Activation of HOLD or AUTO HOLD mode, deactivation NO HOLD.

- Selection using this key or the **III** keys.
- Validation using the W key or after 2 s.

Activation, deactivation of the **SURV** (surveillance) mode. A long press opens a window for viewing the most recent records. Closed by a short press.

Activation, deactivation of the **MEM** (automatic recording) mode. A long press opens the **MEM Function menu.**

2 utility keys



Back-lighting of the display in dark environments. A long press opens the menu for adjusting the **contrast** on the LCD.

Selection of the functions for the **3 secondary displays**.

- Selection by successive presses on this key.
- A long press can be used to exit from this mode.

Description of the instrument (cont'd)

Inputs			
VΩ- -→	Input for voltage and frequency measurements, diode tests, resistance measurements, continuity tests, and capacitance or temperature measurements.		
Α	Input for current measurements.		
СОМ	Reference input.		
Display	 The multimeters in this range are equipped with a graphical LCD screen (58 mm x 58 mm) with 160 x 160 resolution for comfortable reading. 		
	• Reading of the LCD can be optimized by varying the orientation of the display, the adjustment of contrast and, if necessary, using the backlighting.		
_	 The modes, the functions selected, the electrical or physical values measured and the alert symbols are clearly shown on the display. 		
(foot of the screen)	 The user can call up help (i) regarding the function selected. 		
	 The main display is accompanied by its sign and the unit. 		
	Depending on the current selections, the display may be graphical or digital:		
Graphical display	The graphical window can be used to monitor the evolution of the principal measurement.		
	► Example Auto		
4	1.5000 v Main display		

The graphical window and the bargraph constantly track the evolution of the measurement in the range selected.





The main display and the bargraph constantly track the evolution of the measurement.



Functional description

Preparation for use		
Instructions before activation	To use this instrument, you must comply with the usual safety rules in order: - to protect you against the dangers of the electric current, - to protect the multimeter against incorrect operations.	
	For your safety, only use the leads delivered with the instrument. Before using it, systematically check that it is in perfect condition.	
Instrument power supply	 The 3 multimeters in this range operate with three 1.5 V alkaline batteries (LR6-AM3 AA) or three 1.2 V Ni-MH rechargeable batteries (accumulators) of the same type: 	
	The MTX 3281 is delivered with three 1.5 V alkaline batteries (LR6-AM3 AA). It can operate with accumulators, but does not allow in situ recharging (see §. Accessories delivered as options).	
	The MTX 3282 and MTX 3283 multimeters are delivered with three 1.2 V Ni-MH accumulators and charger (12 VDC 7.2 VA) for mains operation whilst simultaneously charging the batteries.	
	 When the charger is connected directly to the instrument, the accumulators can be recharged without removing them from the multimeter. 	
	• The multimeter can only operate if the accu./batteries are in place.	
Power on 🔘	Using the key opposite.	
Charge indicator	A charge status indicator for the batteries or accumulators is constantly shown on the display:	
	Batteries or accumulators > 75 % charged	
	Batteries or accumulators > 25 % charged	
	□ i minimum charge level < 25 %	
	The symbol flashes on the display and a buzzer sounds if the power voltage is insufficient (only 30 min charge life).	
	the batteries or recharge the accumulators (see next page).	
8	There can be differences between the display of the charge level (symbol) and the real charge level of the accumulators, according to the quality and the performances of those.	
	To avoid this risk, we recommend to use same accumulators (HX0051) as those delivered by the manufacturer (see p. 43).	

When getting started, the apparatus needs a few seconds to display a correct level of charge (symbol).

Selection of energy type

For correct management of the battery or accumulator charge status indicator, the type of power must be selected:

- Opening of the **Configuration** menu with the *w* key.
- Selection of the "General" function using the LIL keys.
- Validation of **General settings** using the W key.

Configuration	
General	•
Measure	•
Func. 🙂	•
Func. MATH	•
General settin	gs 🔹

• Selection of **Energy Type** menu using the **W** keys.

General	•
IR baud	9600
Config	user
Energy	bat.
Accumulato	r 🛶
Energy type	

- Modification of the Energy Type (battery or acc.) using the key.
- Validation and exit from the successive menus using the *w* key.

Recharging the accumulators

Before carrying out this operation, check that the accumulators are fitted in the instrument ; they do not need to be removed from the multimeter to be recharged.

Recharging is only possible if "Accumulator" has been selected in the Energy Type menu (see above).



es)

If you try to recharge the accumulators when the batteries are fitted in the multimeter, it could damage it.

For safety reasons, the accumulators should only be loaded at between 0 and $40^\circ\text{C}.$

Caution High internal temperature due to a current measurement may trigger the thermal security mechanism.

Recharging the accumulators (cont'd)

- Before carrying out this operation, select the capacity of the accumulators (2400 mAh by default) fitted in the instrument:
- Selection: Accumulator in the using the **U**
- Validation: Accumulator using the wey, opens a menu for setting the accumulator capacity (in mAh):



- Selection of the digit to be modified using the W key
- Modification of the value using the WU key.
- Validation of the accumulator capacity and exit from the successive menus using the key

To maintain the accumulators in good condition, run the accumulators down to the minimum charge level **before recharging**.

- Then connect the power pack (12 VDC, 7.2 VAC) to the jack connector (see front panel illustration).
- Connect the power pack (12 VDC, 7.2 VAC) to the mains supply.

The symbol opposite on the display allows you to monitor the charge status.

The accumulators are fully charged when the symbol is full **EEEE**.

The **MTX 3282** and **MTX 3283** multimeters contain Ni-MH accumulators. These accumulators must be disposed of by a recycling firm or a company specialized in the treatment of dangerous waste materials.

Never dispose of these accumulators with other solid waste. For further information, contact your MANUMESURE dealer.

When the multimeter is delivered, the accumulators may be discharged, requiring a complete recharge.

Recharging the accumulators with multimeter off Do not connect the wall plug when there are disponible batteries in the instrument.
 Connection of the wall plug starts recharging the accumulators.

The **scrolling** symbol shows the progress of recharging.

Once the accumulators have been fully recharged, the instrument shuts down automatically.

Functional description (cont'd)

Wall plug power unit	Use only the charger that is delivered with this device, which is a 2nd generation multimeter. The charger from the previous generation is not compatible.		
Recharging totally discharged accumulators or new batteries	 Fit the batteries into the multimeter, then connect the charger. Wait approximately 30 minutes, then press the ON button to switch on the multimeter and follow the progress of the charge. Average charging period : 7h30 (with 2400 mAh accumulators) After one effective hour of recharging, the multimeter can be used for measurements, by pressing again on the ON button. 		
"A measurement" protection fuse	A fuse provides protection up to 11 A for current measurements. It must be replaced only with an identical fuse: 11 A, 20 kA, 1000 V, 10 x 38 mm (High Interrupting Capacity).		
Checking of current measurement fuse	 Test the current measurement as follows: Select the Ampere function using the A key. Connect a lead to the A terminal. Check that the LEADS indication disappears from the display (presence of lead). If this is not the case, replace the fuse. 		
Replacement of the fuse or the batteries	 Before replacing the fuse or batteries, comply with the safety instructions given at the beginning of this manual. Then: Disconnect the test leads from the measurement circuits and the instrument. Disconnect the power lead from the MTX 3282 or MTX 3283 12 VDC power pack. Switch off the power to the instrument. Undo the screw on the back of the instrument. Pivot the rear cover of the casing to access the battery/fuse compartment. Remove the fuse or batteries and replace them with identical models. Replace the cover and retighten the screw. Without batteries, the date and time are kept for ca. 1 min in the instrument. The measurements recorded are kept for an unlimited time. 		
Dismantling of multimeter and access to battery/fuse compartment	batteries		

slit for screwdriver

Initial settings

The general menu configures the parameters of the multimeter according to the conditions of use and the user's preferences.

- Opening of the Configuration menu with the *wey*.
- Selection of the **General** menu using the **W** keys and then the **W** key.



Choice of language

Setting the date and time

Selection of the language for the multimeter's menus. Two options are available: French (**Fr**) or English (**En**, default).

Selection of the variables using the key.
Modification of the value using keys.
Clock validation and start-up when menu is closed using key.

Activation of the buzzer (Beep)

Validation (default), or not , of audio signal (beep) when:

- a key is pressed,
- there is a voltage of more than 60 VDC or 30 VAC on the "V" input,
- a stable measurement is acquired in AUTO HOLD mode,
- the power supply voltage (battery) is insufficient.
- ${}^{
 m d}$ The audio signal is maintained even when the buzzer is deactivated :
 - * during continuity testing,
 - * when the range is exceeded (voltage or current),
 - * on a 10 A measurement,
 - * if the position of the leads and the function selected are incompatible.

Validation (default), or not, of automatic shutdown (**sleep**) after 30 min if there has been no action on the multimeter's front panel during that time.

In **SURV**, **MEM** and **Communication modes**, automatic shutdown is not validated.



Automatic

For your safety, automatic shutdown is inhibited when the values measured (voltage, current) on the inputs exceed the danger thresholds (*indicator opposite displayed*).

Display contrast

shutdown (sleep)

Contrast	Modification of the value (default: 50 %)
	 using the vertice key. Validation of setting using vertice key.

A long press on even directly opens the menu, and validates the setting.

Adjustment of back-lighting Selection of the **back-lighting** deactivation time to limit the multimeter's energy consumption.

6 times are possible: 10 s, 30 s, 1 min, 2 min, 10 min or infinite (no deactivation).

By default, the back-lighting deactivation time is 2 min.

Start-up configuration (Config)

- In **user mode**, the instrument restarts with the user's personal configuration and the main function selected when it was switched off.
- In **basic** mode, by default, the multimeter restarts with its elementary configuration and the Volt (AC+DC) function.
- Restart configuration indicated without leads connected. If the leads are connected, they will be taken into account for function selection.

Using the Measure menu, you can adapt the instrument's configuration to the measurement environment:

FilteryesImpedance1GdBm REF•W REF•	 with the <i>key</i>. Selection of the Measure menu using the <i>keys</i> and then the <i>key</i>.

Filter Activation of a **filter** to improve frequency rejection for measurements in low VDC mode.

By default, filter active.

Impedance Choice of the required input **impedance** on the 100 and 1000 mV (1 V) ranges. - 100 mVDC and AC+DC range: 2 possible impedances: 1 G Ω or 10 M Ω

- 1000 mV mVDC range: 2 possible impedances: 1 G Ω or 20 M Ω
- $\overset{d}{=}$ By default, 100 mV range = 10 M Ω , 1000 mV range = 20 M Ω

Adjustment of the reference resistance value (dBm REF) between 1 Ω and 10,000 Ω , for measurements in dBm on VAC or VAC+VDC voltages:



- Selection of the digit to be modified using the W key.
- Modification of the value using the WW keys.
- Validation of the reference resistance in dBm and exit from the menu using the *m* key.

\oint Default value 600 Ω .

<u>Reminder</u>

dBm REF

MTX 3283

er A 0 dBm measurement with a 600 Ω reference resistance is given on a voltage of 0.7746 VAC.

Specific configurations of the instrument

<i>W REF</i> MTX 3283	Adjustment of the reference resistance value (W REF) between 1 Ω and 10,000 Ω for resistive power measurements:		
	The calculation performed is: $(voltage measured)^2 / W REF$ (unit W) (current measured) ² * W REF (unit W) The adjustment procedure is the same as for the dBm reference resistance. Default value 50 Ω . W REF is used to calculate the resistive power (W) with REF = W REF and to calculate the power (V * A) when V (Ref) = W REF		
Initialization of the values	<text></text>		



Default values

General	Language :	Fr	Beep :	on
	Sleep :	on	Contrast :	50 %
	Lighting :	2 min	Communication :	IR
	IR baud :	9600	Configuration :	basic
	Energy 3281 :	battery	Energy 3282, 3283	: accu.
	Accu. capacity :	2400 mAh	Communication pro	otocol : MODBUS
Measure	Filter :	active	Impedance :	10 / 20 M
	dBm REF :	600 Ω	<u>W REF</u> :	50 Ω
Favourite func.	Function :	V	Unit :	none
MATH func.	Coef. A :	1	Coef. B :	0
MEM func.	Recording freq. :	1 s		
	No. of rec. 3281 :	158	No. of rec. 3282, 3	<mark>283</mark> :1000
Main func.	<u>V, A</u> : AUTO,	AC+DC	<u>Hz</u> :	10 V range
	Ω, Capacity:	AUTO	° <u>C</u> :	° C, Pt 100

Access to main functions

Connection of leads

```
The input terminals are limited to 3 : COM, V, \Omega, \rightarrow + and A. Connect the black lead to the COM socket (for all measurements).
```

Functions authorized when connected on the V $\Omega \rightarrow$ terminal



Voltage measurement (Volt).

PEAK is displayed when a peak (Pk+ Pk-measurement) of voltage is detected and when it is higher than the range of active voltage.





A 1st press gives access to Resistance measurements (Ohm).

A 2nd press gives access to **Continuity** measurements (\downarrow).

A 3rd press gives access to **Diode** measurements (+).



A 1st press gives access to **Temperature** measurements (according to the last configuration of the function).

A 2nd press gives access to the type of temperature measurement: ° C, ° F, K.

Selection using the III keys, validation using the Vey or after 2 s.

Another press on this key while selecting the measurement type gives access to **the type of sensors**:

- platinum probes: Pt100 or Pt1000 only on MTX 3282, MTX 3283

- thermocouples: J or K (TC J, TC K)

Selection using the \blacksquare keys, validation using the \boxdot key or after 2 s.



Measurement of Capacitance.



"Favourite" measurement configurable by the user.

For the menu's configuration, see §. 🙂 Function.



Instrument Configuration menu.

Current (AC + DC) measurement.

Functions authorized when connected to the A terminal



Current measurement (Ampere)

The current measurement may be performed using autorange (AUTO PEAK) over the whole scope of the ranges (μA, mA, A).

without a protection fuse, the **LEADS** symbol flashes on the display.

When the red lead is connected to the A terminal, it automatically selects

PEAK is displayed when a peak (Pk+ Pk- measurement) of current is detected and when it is higher than the range of active current.

If current measurement is selected without connection of a lead to terminal A or



"Favourite" measurement configurable by the user.

Instrument Configuration menu.

Range management	The Range key gives access to three operating modes: - AUTO mode - AUTO PEAK mode MTX 3282, MTX 3283 - MANU mode
	 Selection using this key or the IIII keys.
	 Validation using the ⁽¹⁾ key or after 2 s.
	If the measurement is single range, the range defined is forced and there is no
	effect if the Range key is pressed.
	Example: Diode test, continuity test and temperature measurement.
"AUTO" mode	On the input for a measurement, AUTO mode is active by default and range selection is managed automatically by the multimeter.
"AUTO PEAK" mode MTX 3282	In AUTO PEAK mode , the range changes are performed on the basis of rapid acquisition of peaks, either upward or downward.
MTX 3283	AUTO PEAK mode is only accessible for AC, AC+DC in V and A measurements. It prevents untimely overruns of the peak factor specified for the instrument.
"MANUal" mode	When this mode is selected and is valid for the function concerned, the MI
	Measurements concerned: voltage, current, resistance, capacitance.
	By pressing one of the WW keys, you can switch directly to MANUal mode and then modify the range.
Display hold management	The Hold key gives access to two operating modes: - HOLD mode - AUTO HOLD mode - NO HOLD deactivates the mode.
	Selection using this key or the Keys.
	 Validation using the ⁽¹⁾ key or after 2 s.
HOLD	HOLD mode freezes on the screen the current main measurement at the time when the key is pressed. The instrument continues to manage the measurements and display them in the graphical window or on the secondary display (REL mode).
	The range selection remains unchanged: AUTO or MANUal depending on the configuration when you enter this mode.
AUTO HOLD	AUTO HOLD mode automatically freezes on the screen the current main measurement whenever a stable measurement is detected. It is confirmed by a beep (unless the configuration "Beep <i>no</i> " has been selected in the Configuration menu).
	The values memorized remain displayed until the next stable measurement taken (measurement different from ± 100 digits) or until deactivation of AUTO HOLD mode .
	The instrument continues to manage the measurements and display them in the graphical window or on the secondary display (REL mode).
	The range selection remains unchanged (AUTO or MANUal) depending on the configuration when you enter this mode. AUTO HOLD mode is only accessible for V and A measurements.

- **REL** mode takes the current main measurement as its reference. It is indicated on the secondary display: **REF**.
 - The main display continues to indicate the instantaneous value measured and the bargraph.
 - The secondary display ∆ indicates the absolute deviation between the instantaneous value measured and the reference recorded.
 - The secondary display △ % indicates the relative deviation in % between the instantaneous value measured and the reference recorded.
 - Range management may be "AUTOmatic" or "MANUal, depending on the configuration when entering this mode.
 - The *A* and *A* % displays are managed in the same range.
 In "AUTO" mode, they cannot fall below the reference range when the REL mode was activated.
 - Example: Measurement of a 1.5 VDC voltage with a reference set to 1 V:



Adjustment of the reference

When the mode is active, a long press on the **Ref** key opens a window for setting the **REF reference**.

- The Wey selects the digit to be modified.
- The LLL keys modify the digit selected.
- The *w* key can be used to exit from the menu after validating the new reference.

🖎 Example:



- SURV
 - The **SURV** mode monitors the variations of a signal by recording the extreme values (**MIN** and **MAX**) of the main measurement and calculating the average (**AVG**). For each value memorized the multimeter records the corresponding date and time.
 - When it is started up, the MTX 3281 reinitializes the date and time (01:01:2000, 00:00:00).
 Before starting work, set the correct date and time to "date-stamp" the records see §. Setting the date and time).
 - When you enter **SURV** mode by a short press on the key, the last **MIN** and **MAX** measurements are erased and then initialized with the current measurement.
 - SURV flashes when the mode is active.
 - AVG shows the average of all the measurements recorded since SURV mode was activated.
 - The data recorded can be viewed by a long press on the survey key during surveillance or after exiting from the mode.
 - In SURV mode:
 - MANU or AUTO range management cannot be selected.
 - the current measurement, the MIN value and the MAX value are presented in the most suitable range for each of them.
 - 🖎 Example:



Surv

SURV

Start : 27/03/2005	10 :07 :11
Stop : 27/03/2005	10 :10 :30
Mini : -1.0000 27/03/2005	V 10 :08 :25
Max : 2.5000 27/03/2005	V 10 :09 :25
Avg: 1.3000	V

Consultation of recorded data by a

long press on the key

The data recorded is accompanied by the date, time and surveillance range.

• Exit from consultation by a short

press on the

SPEC

On the basis of the technical specifications, the **SPEC** mode directly displays the tolerance of the measurement in progress, so that there is no need to search for it and calculate it.

On the basis of the main measurement, the display:

- indicates the specifications (x % of reading ± n digit) according to the type of measurement, the range selected and the frequency (in AC and AC+DC)
- calculates the interval containing the true value, if the instrument is within its tolerance:
 SMIN value → minimum specification





In AC+DC, the specifications are calculated only if the frequency can be measured (see §. secondary Functions) and is > 45 Hz.

- **MEM MEM** mode records the contents of the digital display(s) in the memory of the instrument at a pre-programmed rate.
 - A short press on starts a series of recordings.
 - The **MEM** symbol flashes throughout the recording period; it is accompanied by the number of recordings made.
 - Memorization of the measurements can be stopped by another short press.
 - The number of values to be memorized for a measurement run is programmable: it therefore stops recording automatically.
 - Another press on starts a new series of recordings.

MTX 3281		158 measurements per sequence	1 to 10 sequences	
MTX 3282, MTX 3283	Recording capacity	6500 measurements maximum	1 to 10 sequences (depending on available memory)	
Example: activation of MEM mode during surveillance mode	AUT	-1.0000 V 2.5000 V	• Furthermore, the MEM mode may be activated during the SURV mode or during display of the secondary functions. The parameters set are saved. It will then be possible to	

- **3000** V SURV MEM 2
- (When it is started up, the MTX 3281 reinitializes the date and time (01:01:2000, 00:00:00).
 Before starting work, set the correct date and time to "date-stamp"

Before starting work, set the correct date and time to "date-stamp" the records. See §. Setting the date and time).

AVG

Configuration of MEM mode The **MEM** mode is configured in the **Func. MEM** function of the **Configuration Menu.**

- Opening of the **Configuration** menu with the *w* key.
- Selection of the "Func. MEM" function using the Meys.

		Measure Func. Func. MATH	
		Func. MEM 🗕	
		Function MEM settings	
	Validation of Fun	nc. MEM using the 👁 key.	
	d Iong press on	Mem opens the MEM Function m	enu.
Programming	 Selection of the "l 	RATE" function using the III keys.	
the recording frequency		MEM Function	
		Consult + Erase +	-
		Erase all erase	
		Rate 🕂	
		Recording rate	-
	 Validation of Rate recording rate in I 	with the 🖤 key opens a menu for s nours, minutes and seconds:	etting the required
		Rate h:mn:s	
		00 : 00 : 02	
	Selection of the	variables, hour, minute, second, usin	ig the 👁 key.
	 Modification of the r Validation of the r menus using the 	e value using the DD keys. neasurement recording rate and exit the key 2007.	from the successive

The minimum recording rate is 23 h, 59 min, 59 s. Default recording rate 1s.

Programming of the number of records By defining a number of records for a measurement campaign, it is possible to stop recording automatically.

• Selection of the number of records (**No. rec**.) in the **MEM Function** menu using the keys



- Selection of the digit to be modified using the ⁽¹⁾ key.
- Modification of the value using the **W** keys.
- Validation of the number of records and exit from the successive menus using the *m* key.

<u>Reminder</u>

The recording capacity is limited to 6,500 measurements (158 for MTX 3281)

Number of records by default : 1,000.

<u>Reading the</u> recorded data

Recordings	
28/03/05	10:40:40
28/03/05	10:41:08
29/03/05	11:05:20
30/03/05	15:30:42
5 val. (2 s),	V

• Select the **Consult** menu in the **MEM Function** to view the list or successive records.

Each recording is identified by its start date and time.

• Selection of a recording using the kevs.

• Validation the selection using the

key.

- When selected, a recording is accompanied by :
 - the number of values recorded,
 - the recording rate,
 - the function in which they were recorded,
 - the secondary functions present during recording, if relevant.

<u>Reminder</u> The number of recording sequences is limited to 10.

Viewing the data in a recording The curve displayed is adapted to the graphical window according to its min. and max. values and the number of recordings.



Access to secondary functions

886888

Choice of secondary functions on the two displays 2, 3 and 4 by pressing successively on the key opposite according to main measurement. A long pressing deletes the display of secondary measurements.

For the main authorised measurements, the last combination selected for displays 2, 3 and 4 is memorised and will be directly reactivated.

Table of secondary functions Refer to page 9.

efer to page 9.	Display 2 Display 3		Disp	olay 4	Display 1: Main measurement			nt				
	Function	n Unit	Function	Unit	-	-	VAC VAC+DC	VDC	AAC AAC+DC	ADC	Hz	Ω
MTX 3281 / 2 / 3	FREQ	Hz	PER	S	Func.	MATH	х		х			
MTX 3283	FREQ	Hz	dB	dB	Func.	MATH	х					
MTX 3283	dBm	dBm	REF (dBm)	Ω	Func.	MATH	х					
MTX 3281 / 2 / 3	Pk+	V or A	Pk-	V or A	CF	-	х		х			
MTX 3283	w	W	REF <i>(Ω</i>)	Ω	Func.	MATH	x	х	x	х		
MTX 3281 / 2 / 3	PER	S	DC+	%	Func.	MATH					х	
MTX 3281 / 2 / 3	PER	S	DC-	%	Func.	MATH					х	
MTX 3282 / 3	PW+	S	CNT+	-	Func.	MATH					х	
MTX 3282 / 3	PW-	S	CNT-	-	Func.	MATH					х	
MTX 3282 / 3	Func. N	IATH	-	-		-						х
MTX 3282 / 3	V x A	VA	Α	А	Func.	MATH	x (*)	х				
	1								1			

Function **MATH** = y = Ax + B (**MTX 3282, MTX 3283**)

- **FREQ** = Frequency measurement
- **PER** = Period measurement
- dB = Measurement of voltage decibels in dB
- dBm = Measurement of power decibels in dBm with REF = dBm REF
- **Pk+** = Measurement of positive peaks (**)
- **Pk-** = Measurement of negative peaks (**)
- CF = Measurement of peak factor
- **w** = Calculation of resistive power with REF = W REF
- V x A = Calculation of power (*) limited to 400 Hz
- **DC+** = Measurement of positive duty ratio \Box
- **DC-** = Measurement of negative duty ratio
- **PW+** = Measurement of pulse-width or of positive durations ____
- **PW-** = Measurement of pulse-width or of negative durations
- **CNT+** = Counting of positive pulses $___$ (**)
- **CNT-** = Counting of negative pulses ___ (**)
- (**) Measurement reset to zero: by pressing on 🖤 key.
- For optimal use, refer to §. Technical Specifications.

Access to secondary functions (cont'd)

MTX 3283

Upon activation of **dB** measurements, the value measured is taken as voltage reference (V ref).

The calculation is as follows:

20 log₁₀ (V measured / V ref).

d The voltage reference (V ref) cannot be modified.

The MATH function is displayed when its parameters allow it (see MATH Func.).

For the dBm and resistive power measurements, see **Measurement** menu for the adjustment of related reference resistances (**dBm REF, W REF**) and to know the calculation formulas.

MTX 3282 MTX 3283

The calculation of power $V \times A$ (VA) requests a 3rd connection to the A input (connected to the same circuit) in order to measure simultaneously: DC voltage (main display), DC power (display 3, measurement always in AC+DC).

The link on the COM input must be short and have a large diameter in order to limit the voltage drop which influences the Volt measurement.



- Volts

MATH function

MTX 3282 MTX 3283

Adjustment of MATH function

- The MATH function (y = Ax + B) enables measuring any physical quantity in:
 - (0 10 V process or high-voltage probe, for example)
- Amperes (current loop 4 20 mA or current clamp, for example)
- **Frequency** (output measurement, rotation speeds, for example)
- **Ohms** (resistive position, for example)

and converting it and to assign the adequate unit, to obtain the direct reading of the original parameter on the instrument. Depending on the parameter measured, the device calculates the related MATH function.

The programming takes place in 4 phases:

Selection of parameter X measured (V, A, Ω , Hz) Definition of coefficient A of function y = Ax + B Definition of coefficient B of function y = Ax + B Definition of physical unit to be displayed

Coefficients A, B and the unit are programmable for each amount measured (V, A, Ω , Hz).

The MATH mode is configured in the MATH function in the Configuration Menu.

- Opening of **Configuration** Menu using key *2*.
- Selection of function MATH Func. using keys

Configuration	
General 🕂	
Measure 🕂	
Func. 🙂 🛛 🕂	
Func. MATH 🕂	
MATH function settings	•

• Validation of MATH Func. using key 🔍

Selection of Function menu using keys

Selection of function to be adjusted

MATH function						
Function	V					
Coef A	•					
Coef B						
Unit	•					
Function to be set						

- Selection of measurement (V, A, Ω, Hz) using key W.
- Default function V.

Definition of coefficient A

- The MATH function applied to the physical quantity (x) measured is y = Ax + B.
- Selection of the coefficient A menu (**Coef A**) in MATH function.
- Validation of Coef A (coefficient A) using key



- Selection of digit to be modified or of exponent using key ^O.
- Modification of value using keys
- Validation of coefficient A and menu exit using key 2.
- Coefficient A by default is 1.

Definition of coefficient B

- Selection of coefficient B menu (Coef B) in MATH function.
- Validation of **Coef B** (coefficient B) using key .



- Selection of digit to be modified using key ^O.
- Modification of value using keys
- Validation of coefficient B and menu exit using key 2.
- d Coefficient B by default is 0.

Definition of unit

The unit of the MATH function may be defined so as to obtain the direct reading of the original physical quantity measured by the instrument.

- Selection of Unit menu in MATH function.
- Validation of Unit using key



- Selection of letter or character to display using key .
- Validation of letter or character using keys
- Validation of the unit (3 characters max.) and menu exit using key 2.

The symbol 🔺 is used to switch from uppercase letters to lowercase.

The symbol 🔄 is used to erase the last character.

MATH unit by default (without).

Function 😳	The favourite function \textcircled recalls directly the specific measurement you use most frequently and that you will have carefully defined previously. This function is of the same type as the MATH function (y = Ax + B). When you measure any physical quantity, this function enables you to convert it and to assign the appropriate unit, to obtain the direct reading of the original amount on the instrument. Depending on the amount measured, the device calculates the related function \textcircled , if the parameters of the latter correspond to the amount measured.					
	 Programming takes place in 4 stages: 1. Selection of the amount X measured (V, A, Ω, Hz) 2. Definition of coefficient A of function y = Ax + B 3. Definition of coefficient B of function y = Ax + B 4. Definition of the physical unit to be displayed 					
Application of the favourite function acc. to its programmed measurements (V, A, Ω, Hz)	 Access to the type of measurement using key © AC, DC or AC+DC for measurements V and A Access to the frequency range using key © Frequency < 900 kHz (default) or > 900 kHz for Hz measurements Control of operating modes using key Range: AUTO, AUTO PEAK, MANU for V and A measurements AUTO, MANU for Ω measurements <i>Pressing one of the keys will switch directly to MANUal mode, then modify the range for measurements V, A and Ω. Modification of the voltage range for Hz function.</i> Control of display holding using key <i>Mod</i>: HOLD, AUTO HOLD, NO HOLD for V and A measurements HOLD, NO HOLD for Ω, Hz measurements Activation, deactivation of monitoring mode using key <i>Man</i> 					
<u>Adjustment of</u> <u>function ☺</u>	 The function is configured in Func. ⁽ⁱ⁾ in the Configuration Menu. Opening of Configuration Menu using key ⁽ⁱⁱⁱ⁾. Selection of function Func. ⁽ⁱ⁾ using keys ⁽ⁱⁱⁱ⁾. Validation using key ⁽ⁱⁱⁱ⁾. 					
	Configuration General Measure Func. ⓒ Func. MATH Function ⓒ setting					

A long pressing on been s directly the Function 🙂 menu.

ø

Selection of adjustment parameters Selection of adjustment parameters using keys



<u>Selection of amount</u> <u>measured (function)</u>

- Selection of Function menu using keys
- Selection of amount measured (V, A, Ω, Hz) using key
- Default function V.

Definition of coefficients A, B and unit

The O favourite function applied to the physical quantity (x) measured is the same as the MATH function (y = Ax + B).

For the definition of coefficients A, B and the **unit**, see the related menus of the MATH function.

Coefficient A is by default 1, B by default 0, unit by default (without).

Example: activation of favourite function and automatic recording mode



- Symbol 🙂 of favourite function
- AUTO Mode active
- DC Measurement
- W Unit
- MEM Mode active

SX-DMM Software kit	These multimeters can interface directly with a computer or a PC using the SX-DMM software kit (HX0050 option):				
(option)	 In the menu General settings of the multimeter: Select infra-red communication (IR by default) using the Comm function. Select Modbus communication protocol. Select the infra-red transmission speed using the IR baud function: 9600 / 19,200 / 38,400 Bauds/s. 				
Connection of optical cables RS232-DB9F or USB (option)	He transmission speed by default is 9600 Bauds/s.				
	The other transmission parameters are set (8 data bits, 1 stop bit, no parity).				
	 Then connect the optical cable to the optical input of the multimeter (located next to the multimeter inputs). A mechanical failsafe prevents reversing of the connection direction. Connect cable RS232-DB9F or USB to one of the corresponding inputs of the PC 				
(opacity)	2 Verify that the RS232 interface parameters of the PC are identical to				
	those of the multimeter.				



For the USB optical cable (option), install, if necessary, the recognition software on your PC (see CD-Rom manual provided).

Installation of SX-DMM software

- 1. Install the SX-DMM software on the PC using the CD ROM.
- 2. Launch the software to perform data acquisition and study the different display possibilities (curves, tables...).
- The symbol (RS232) flashes on the display during control of the instrument from the PC (REMOTE mode).

For more information, refer to software help menu.

In this mode, the multimeter keyboard is locked, except for key which is used to exit this mode.

Bluetooth (on -BT version)	The -BT versions of the multimeters are fitted with a Bluetooth module. They integrate the Serial Port Profile service used to communicate with a computer fitted with any type of Bluetooth adapter.
	If your computer does not have a Bluetooth module, the PC USB/Bluetooth adapter (P01637301 <i>)</i> is required. To install these pilots, <i>refer to the accompanying instructions.</i>
	Virtual RS232 serial communication between the multimeter (Server) and the PC (Customer) requires a connection on the PC side.
	No configuration is required on the multimeter side, except for activation of Bluetooth (BT) communication via the Comm. function in the General Settings menu.

æ

Bluetooth (cont'd)

Creating a Bluetooth connection

(fo connection of

(for first	Steps	Actions						
connection only)	1 Power up the multimeter.							
	2	Configure it for Bluetooth (BT) via the configuration menu.						
	3	3 Create a new connection using the software controlling your Bluetooth dongle on the PC side by:						
		 clicking on the Bluetooth Manager icon on the menu bar at the bottom of the screen selecting the New connection function 						
		• selecting Express Mode (recommended), then clicking on Next						
		 selecting the Bluetooth peripheral of the multimeter then by clicking on Next 						
		 clicking on Next after configuration of a COM port 						
		 redefining the name of the connection and its icon (if required) then clicking on Next 						
		 clicking on Finish to save the connection information 						
	You can created your PC	verify that the connection has been by viewing it, using the software controlling USB/Bluetooth adapter.						
	For addi linked to	tional information, refer to the Help menu Connect Disconnect						
	🖞 With s valida	some Bluetooth adapters, rebooting of the PC is recommended to the the connection.						
	d The co They i	onnection parameters are specific to each multimeter. must be assigned manually, but only the first time.						
🖎 Example	Communication with SX-DMM software can begin without other Bluetooth configurations. You must simply establish communication between the PC and the multimeter using the COM port configured previously.							
	<u> </u>	<u>innana oktobili ostikare</u> . Sommanication y Faramotoro						
Reactivation of the connection	 Click on the Bluetooth Manager icon on the menu bar at the bottom of the screen 							
after shutdown	• Click on the icon related to the multimeter in the window of the Bluetooth Parameters Software: the icon of the menu bar must be displayed in green.							
Communication with several	The PC L several m	JSB/Bluetooth adapter is used to communicate simultaneously with nultimeters in the MTX Mobile family.						
multimeters	For each multimeter, you must repeat the previous configuration procedure, while making sure to assign them a different COM port.							
	Depending on the type of adapter, first make a COM port available.							

To activate connection with the multimeter, the Bluetooth identifying code is " 0000

The controls cited below are those of the PC USB/Bluetooth adapter

(P01637301). They may be designated differently on another adapter.

Technical specifications

Digit" (as per CEI 485)

Voltage measurement

AC voltage VAC and VAC+DC TRMS

æ

Accuracy: Only the values assigned a tolerance or a limit constitute guaranteed values. "n% +nD" means Values without tolerance are given for information (standard NFC 42670). "n% of reading + n The technical specifications are guaranteed only after 30 min warm-up period. Except special indication, they are valid from 5 to 100 % of the range of measurement.

> On this position, you measure the true RMS value of an AC voltage with its DC component (no capacitive coupling): so-called TRMS measurement.

- The 100 mV range is present in MANUal mode only. •
- In VAC & VAC+DC modes and for signals > 1 kHz, the uncertainty range is given • for information only : it is recommended to use the formulas below.

x [F(kHz) - 0,4] ± 40D

x [F(kHz) - 4] ± 40D

MTX 3281	Pango	Input	Posolution	Accuracy					
	Range	impedance	Resolution	45 Hz to 1 kHz		1 to 50 kHz (log(10)) = 1)		
	100 mV (*)	1 GΩ - 10 MΩ	1 µV	1 % ± 50D	1 9	% + 5 % x log(1+ 0.18 x [F(kHz	z) - 1]) ± 50D (***)		
(*) in VAC mode	1000 mV	10.5 MΩ	10 µV	1 % ± 30D 1 % + 5 % x log(1+ 0.18 x [F(kHz) - 1]) ± 30D					
(**) 🛆 limitation	10 V	10.5 MΩ	0.1 mV	0.7 % ± 30D	.7 % ± 30D 0.7 % + 4 % x log(1+ 0.41 x [F(kHz) - 1]) ± 30D				
in high frequency	100 V	10 MΩ	1 mV	0.7 % ± 30D	kHz) - 1]) ± 30D				
(***) typical values	1000 V (**)	10 MΩ	10 mV	1 % ± 30D 1 % + 6 % x log(1+ 0.16 x [F(kHz) - 1]) ± 30D					
	Pange	Input	Resolution	Accuracy					
	Range	impedance	Resolution	45 to 400 Hz 400 Hz to 4 kHz 4 to 50 kHz			4 to 50 kHz		
	100 mV (*)	1 GΩ - 10 MΩ	Ω 1 μV	1.5 % :	± 40D	1.5 % + 0.417 %	3 % + 0.065 %		

(*)	in \	VAC	mod	e

MTX 3282	Pange	Range Input		Accuracy				
	rtange	impedance	Resolution	45 Hz to 1 kHz	z 1 to 75 kHz (log(10)=1) 75 to			
	100 mV (*)	1 GΩ - 10 MΩ	1 µV	1 % ± 50D	1 % + 5 % x log(1 + 0.2 x [F(kHz) - 1]) ± 50D (***)	10% ± 50D(***)		
(*) in Vac mode	1000 mV	10.5 MΩ	10 µV	0.5 % ± 50D	0.5 % + 5 % x log(1 + 0.25 x [F(kHz) - 1]) ± 50D	10% ± 50D(***)		
(**) A limitation in	10 V	10.5 MΩ	0.1 mV	0.3 % ± 50D	0.3 % + 6 % x log(1 + 0.16 x [F(kHz) - 1]) ± 50D	10% ± 50D		
high frequency	100 V	10 MΩ	1 mV	0.3 % ± 50D	0.3 % + 6 % x log(1 + 0.16 x [F(kHz) - 1]) ± 50D	10% ± 50D		
(***) typical values	1000 V (**)	10 MΩ	10 mV	0.3 % ± 50D	0.3 % + 6 % x log(1 + 0.16 x [F(kHz) - 1]) ± 50D	10% ± 50D		

	Range Input impedance	Posolution						
(*) in VAC mode (***) typical values from 50 kHz	Range	input impedance	Resolution	45 to 400 Hz	400 Hz 400 Hz to 4 kHz 4 to 100 kHz			
	100 mV (*)	1 GΩ - 10 MΩ	1 µV	1.5 % ± 40D	1,5 % + 0,417 % x [F(kHz) - 0,4] ± 40D	3 % + 0.065 % x [F(kHz) - 4] ± 40D (***)		

MTX 3283	Range					Accuracy				
		Input impe	dance	Reso	olution	45Hz to 1kHz	1 to 100 kł	Hz (log(10) = 1)	1	100 to 200 kHz
	100 mV (*)	1 GΩ - 1	0 ΜΩ	1	μV	1 % ± 50D	1 % + 8 % x log(1+ (0,06 x [F(kHz) - 1]) ± 50l (***)	D 1	15% ± 50D(***)
(**) 🛆 limitation	1000 mV	10.5 N	lΩ	10) µV	0.5 % ± 40D	0.5 % + 5 % x log(1+ 0	,2 x [F(kHz) - 1]) ± 50D	1	15% ± 50D(***)
in high frequency	10 V	10.5 N	1Ω	0.1	1 mV	0.3 % ± 30D	0.3 % + 8 % x log(1+ 0	,06 x [F(kHz) - 1]) ± 30D) 1	15% ± 30D
(***) typical values	100 V	10 M	Ω	1	mV	0.3 % ± 30D	0.3 % + 8 % x log(1+ 0,06 x [F(kHz) - 1]) ± 30D) 1	15% ± 30D
	Range	Input impedance	Resolu	tion	45	to 400 Hz	Accu	Iracy	50) to 200 kHz
(*) in Vac mode		mpoddiloo			40	10 400 HZ	400 HZ 10 4 KHZ	4 t0 50 kHz	50	% + 0.067 %
(***) typical values	100 mV (*)	1 GΩ - 10 MΩ	1 µ\	/	1.5	5 % ± 40D	x [F(kHz) - 0.4] ± 40D	x [F(kHz) - 4] ± 40D	3 / ×[±	F(kHz) - 50] 40D (***)

AC voltage VAC and VAC+DC TRMS	 (**) BP : Freq [kHz] limited to : 15,000 / U applied [V] U applied [V] limited to : 15,000 / Freq [kHz] >> Example : U applied = 1000 VAC → max. frequency : 15,000 / 1000 = 15 kHz
TRMS	 ▲ Example : 0 applied = 1000 VAC → max. frequency : 15,000 / 1000 = 15 kHz In the presence of a continuous component :
(cont'd)	Additional error : (UDC / U measured) x (0,7% + 70D) ▲ Example : UDC = 2 V, U measured = 5 Vrms → additional error : 0.28% + 28D Rejection: common mode > 80 dB at 50 Hz or 60 Hz depending on selection Automatic or manual selection of ranges. Protection by varistors. Maximum permanent acceptable voltage: 1000 VACrms. Specifications valid from: 20 to 100% of range in the 20 kHz to 200 kHz MTX 3283 MTX 3282 MTX 100 kHz MTX 3282 MTX 3283 Influence of peak factor on accuracy in VAC, VAC+DC at 50% of the range: 1% for a peak factor between 4,5 and 6 5% for a peak factor between 6 and 9

DC voltage In "DC" mode, you measure the value of a DC voltage or the DC component of *VDC* an AC voltage, once the filter is activated, see p. 15.

MTX 3281	Range	Input impedance	Resolution	Protection	Accuracy	
WITX 5201	100 mV (*)	100 mV (*) 10 MΩ / 1 GΩ			0.1% + 30D	
	1000 mV	20 MΩ / 1 GΩ	10 µV			
	10 V	10.5 MΩ	0.1 mV	1450 Vpk	0.1% + 8D	
	100 V	10 MΩ	1.0 mV			
	1000 V	10 MΩ	10 mV		0.2% + 8D	

ø	The	100 mV	range is	present in	MANUal	mode only	٧.
---	-----	--------	----------	------------	--------	-----------	----

MTX 3282	Range	Input impedance	Resolution	Protection	Accuracy
	100 mV (*)	10 MΩ / 1 GΩ	1 µV		0.1% + 30D
	1000 mV	20 MΩ / 1 GΩ	10 μV	0.05% + 8D	
	10 V	10.5 MΩ	0.1 mV	1450 Vpk	0.029/ ± 9D
	100 V	10 MΩ	1.0 mV		0.03% + 6D
	1000 V	10 MΩ	10 mV		0.035% + 8D

MTX 3283

Range	Input impedance	Resolution	Protection	Accuracy
100 mV (*)	10 MΩ / 1 GΩ	1 µV		0.1% + 30D
1000 mV	20 MΩ / 1 GΩ	10 µV		0.05% + 8D
10 V	10.5 MΩ	0.1 mV	1450 Vpk	0.02% + 8D
100 V	10 MΩ	1.0 mV		0.02 % + 0D
1000 V	10 MΩ	10 mV		0.03% + 8D

(*) - Accuracy with filter (p. 15) and REL mode activated (Δ measurement). Recovery after release of the protection (> 10 V) approx. 10 s.
Protection 1 min. max.

Specifications valid from 0 % to 100 % of the range

Rejection: common mode: > 120 dB with 50 Hz and 60 Hz acc. to selection serial mode: > 60 dB with 50 Hz and 60 Hz acc. to selection Automatic or manual selection of the ranges. Protection by varistors.

Current measurement

ADC current МТХ 3

> МТХ 3 MTX 3

In "ADC" mode, you measure the value of a DC current or the DC component of an AC current.

281	Range	put impedance	Resolution	Protection	Accuracy	
282	1000 µA	≈ 170 Ω	10 nA		0.1 % + 15D	
283	10 mA	≈ 17 Ω	0.1 µA			
200	100 mA	≈ 1.7 Ω	1 µA	11 A	0.00 % + 0D	
	1000 mA	≈ 0.17 Ω	10 µA	20 A < 30 s	0.15 % + 8D	
	10 A		100 µA			
	100 A (**)	≈ 0.03 Ω (*)	1000 µA		0.5 % + 15D	

(*) with the fuse delivered with the instrument (**) 100 A range limited to 20 A Specifications valid from 0 % to 100 % of range

AAC current, AAC+DC TRMS In "AAC" and "AAC+DC" modes, you measure the true RMS value of an AC current with/without its DC component (no capacitive coupling in "AC+DC" mode). Т

MTX 3281

Range	put impedance	Resolution	Protection	Accuracy		
runge	put impedance	Resolution	1 Iotection	45 Hz to 1 kHz	1 to 20 kHz	
1000 µA	≈ 170 Ω	10 nA		1 % ± 40D	1 % + 0.25 % x [F(kHz) - 1] ± 30D (***)	
10 mA	≈ 17 Ω	0.1 µA		1 % ± 30D	1 % + 0.1 % x [F(kHz) - 1] ± 30D	
100 mA	≈ 1.7 Ω	1 µA	11 A	1 % ± 30D	1 % + 0.1 % x [F(kHz) - 1] ± 30D	
1000 mA	≈ 0.17 Ω	10 µA	20 A < 30 s	1 % ± 30D	1 % + 0.1 % x [F(kHz) - 1] ± 30D	
10 A	~ 0.03 0 (*)	100 µA		1 % ± 300D	1 % + 0.15 % x [F(kHz) - 1] ± 300D	
100 A (**)	~ 0.03 12 ()	1000 µA	-	2.5 % ± 30D	2.5 % + 0.15 % x [F(kHz) - 1] ± 30D	

MTX 3282

Range	Input	Resolution	Protection		Accuracy	
Range	impedance	resolution	Trotection	45 Hz to 1 kHz	1 to 20 kHz	20 to 50 kHz
1000 µA	≈ 170 Ω	10 nA		0.5 % ± 40D	0.5 % + 0.25 % x [F(kHz) - 1] ± 30D (***)	-
10 mA	≈ 17 Ω	0.1 µA		0.3 % ± 30D	0.3 % + 0.1% x [F(kHz) - 1] ± 30D
100 mA	≈ 1.7 Ω	1 µA	11 A	0.3 % ± 30D	0.3 % + 0.1% x [F(kHz) - 1] ± 30D
1000 mA	≈ 0.17 Ω	10 µA	20 A < 30 S	0.3 % ± 30D	0.3 % + 0.1 % x [F(kHz) - 1] ± 30D	-
10 A	~ 0.03 0 (*)	100 µA		0.4 % ± 400D	0.4 % + 0.15 % x [F(kHz) - 1] ± 400D	-
100 A (**) ≈ 0.03 Ω ()	1000 µA		2.5 % ± 40D	2.5 % + 0.15 % x [F(kHz) - 1] ± 40D	-	

A

MTX 3283

	Input			Accuracy		
Range	impedance	Resolution	Protection	45 Hz to 1 kHz	1 to 20 kHz	20 to 50 kHz
1000 µ/	A ≈ 170 Ω	10 nA		0.5 % ± 40D	0.5 % + 0.25 % x [F(kHz) - 1] ± 30D (***)	-
10 mA	≈ 17 Ω	0.1 µA		0.3 % ± 30D	0.3 % + 0.1 % x [F(kHz) - 1] ±	: 30D
100 mA	≈ 1.7 Ω	1 µA	11 A	0.3 % ± 30D	0.3 %+ 0.1 % x [F(kHz) - 1] ±	30D
1000 mA	≈ 0.17 Ω	10 µA	20 A < 30 S	0.3 % ± 30D	0.3 % + 0.1 % x [F(kHz) - 1] ± 30D	-
10 A	≈ 0.03 Ω	100 µA		0.4 % ± 400D	0.4 % + 0.15 % x [F(kHz) - 1] ± 400D	-
100 A (**) (*)	1000 IIA,	1	2 5,% + 40D	2 5 % + 0 15 % x [F/kHz) - 11 + 40D	_



A max. overload of 20 A is acceptable for 30 s max. with a pause of 5 min at least between each measurement.

From 7 A, the measurement is limited to an ambient temperature of 40° C and a period of 1h30 with a pause of 15 min at least between each measurement.

Specifications valid from 10 % to 100 % of range for sinusoidal current.

Protection 1000 Vrms by ceramic HRC type fuse 1000 V, 11 A > 20 kA Cos ϕ > 0.9 (10 x 38 mm)

Fuse MTX 3282 MTX 3283

 ${rac{d}{d}}$ As soon as the PEAK symbol appears, switch to AUTO PEAK mode :

mA and µA range:

Additional error of 2% for a peak factor between 4.5 and 6 Additional error of 15% for a peak factor between 6 and 9 10 A range: Zero up to peak factor of 6. Voltage drop: 10 A < 400 mV 1 mA $\approx 160 \text{ mV}$ 10 mA ≈ 180 mV 100 mA \approx 180 mV 1000 mA \approx 300 mV

Frequency measurement

Main frequency (Hz)

In this position, you measure the frequency of a voltage. *AC Signals*

MTX 3281 MTX 3282 MTX 3283

281	Range	Resolution	Protection	Accuracy
201	0.8 to 10 Hz	0.0001 Hz		
282	10 to 100 Hz	0.001 Hz		
283	100 to 1000 Hz	0.01 Hz		
	1000 Hz to 10 kHz	0.1 Hz	1450 Vpk	0.02 % ± 8D
	10 to 100 kHz	1 Hz		
	100 to 1000 kHz	10 Hz		
	1 MHz to 2 MHz	100 Hz		

Pange	Sensitivity (applicable on rectangular signals only)						
Range	100 mV	1 V	10 V	100 V	1000 V		
0.8 Hz to 10 Hz	15 % of range	25 % of range	15 % of range	15 % of range	15 % of range		
10 Hz to 100 kHz	10 % of range	20 % of range	10 % of range	10 % of range	10 % of range (*)		
100 to 500 kHz	(**)	20 % of range	typ. 20 % of range	20 % of range (*)	20 % of range (*)		
500 to 1000 kHz			typ. 30 % of range				

(*) Freq [kHz] limited to: U applied [V] limited to: 15,000 / U applied [V] 15,000 / Freq [kHz]

(**) limited to 200 kHz

The measurement is performed by capacitive coupling.

Selection of the manual frequency range < 900 kHz (default) or > 900 kHz,

via a short pressing of the key opposite.

Selection of voltage range in manual mode possible, via a long pressing of the key *opposite*.

Input resistance: \approx 10 M Ω (Freq < 100 Hz)

Maximum permanent acceptable voltage: 1000 Vrms. See (*).

Protection by varistors at the voltage input

Parallel
voltage or current
or frequency
(secondary
function)



You measure the frequency and value of a voltage or a current.

Range	Accuracy	Resolution	Admissible overload
0.8 to 10 Hz		0.0001 Hz	
10 to 100 Hz		0.001 Hz	
100 to 1000 Hz		0.01 Hz	1450 Vdc
1000 to 10 kHz		0.1 Hz	on 500 mV range
10 to 100 kHz		1 Hz	1
100 to 200 kHz		10 Hz	

	Sensitivity (applicable on rectangular signals only) Vrms				
Range	100 mV	1 V	10 V to 1000 V (*)	1000 µA to 20 A (**)	
0.8 Hz to 5 kHz	15 % of range	20 % of range	15 % of range	20 % of range	
5 kHz to 50 kHz	10 % of range	20 % of range	10 % of range	20 % of range	
50 kHz to 100 kHz	15 % of range	25 % of range	15 % of range		
100 111 1: 000 111		00.0/	00.0/	-	

(*) Freq limited to [kHz]: 15,000 / U applied [V] U applied [V] limited to [V]: 15,000 [V * kHz] / Freq [kHz]

(**) limited to 20 kHz MTX 3281 ; at 50 kHz MTX 3282, MTX 3283 for the "Ampere" range

Measurement is performed by capacitive coupling Input resistance: \approx 10 M Ω (Freq < 100 Hz) Protection by varistors at voltage input

Resistance measurement (Ω)

In this position, you measure the value of a resistance.

surement (Ω)

MTX 3281

1 , 2			
Range	Accuracy	Resolution	Protection
1000 Ω		10 mΩ	
10 kΩ		100 mΩ	
100 kΩ		1 Ω	1000 \/rms
1000 kΩ		10 Ω	1000 VIIIIS
10 MΩ	0.5 % + 8D	100 Ω	
50 MΩ	2 % + 8D	1 kΩ	

MTX 3282 MTX 3283

Range	Accuracy	Resolution	Protection
1 000 Ω	0.1 % + 8D	10 mΩ	
10 kΩ		100 mΩ	
100 kΩ	0.07 % + 8D	1 Ω	1000 \/rmc
1000 kΩ		10 Ω	1000 11115
10 MΩ	0.5 % + 8D	100 Ω	
50 MΩ	2 % + 8D	1 kΩ	

Automatic/manual range selection "Active" protection via CTP thermistor Measurement voltage: ca. 1.2 V

Maximum voltage developed on open circuit: 4 V typ

- In range 50 M Ω , in order to avoid the influence of the network and to guarantee the given specifications, it is advised to disconnect the multimeter from Wall Plug.
- For measurements higher than 10 $M\Omega$, a shielded cable is recommended. For a 2 wire-link, use very short wires (< 25 cm) and twist them.

Continuity M	lode (
	MTX 3281
	MTX 3282
	MTX 3283

On this position, you can measure the value of a resistance up to 1000 $\Omega,$ with steady audio indication at 2 kHz.

32	Range	Accuracy	Measuring current	Resolution	Protection
33	Beeper	0.1% + 8D	approx. 0.4 mA	100 m Ω	1000 Vrms

Detection threshold in continuity mode \approx 120 Ω (response time \approx 5 ms). "Active" protection via CTP thermistor.

Maximum voltage on open circuit: 4 V max, 2 V typ.



Indication of junction voltage in the direction from 0 to 2.6 V in a single range (10 V range)

Accuracy	2 % ± 30 D
Resolution	0.1 mV
Measuring current	< 1 mA
Maximum voltage developed on open circuit	4 V max.
"Exceeded" indication	in reverse direction
"Active" protection by CTP thermistor	1000 Vrms

Capacitance					
me	asurement				
(-	-)				

MTX 328 MTX 328 MTX 328 In this position, you can measure the value of a capacitor.

		•		•	
	Range	Accuracy	Resolution	Measurement time	Protection
1 2 3	10 nF (*)	1 % + 10D	10 pF	< 0,2 s	
	100 nF		100 pF	< 0,5 s	
	1000 nF	1 % + 5D	1 nF	< 2 s	1000 Veff.
	10 µF		10 nF		
	100 µF		100 nF		
	1000 µF	1 % + 15D	1 µF	E o/mE	
	10 mF	1.5 % + 15D	10 µF	≈ 5 S/IIIF	

(*) Use the REL function for values < 10 % of range to reset to residual zero (compensation of the test lead capacity)

Resolution of 1000 points.

Automatic/manual range selection.

"Active" protection by CTP thermistor. Maximum voltage delivered on open circuit: 1 V typ. / 4 V max.

For measurements lower than 10 nF, a shielded cable is recommended. For a 2 wire-link, use very short wires (< 25 cm) and twist them.

Temperature measurement with Pt 100 or Pt 1000

MTX 3282 MTX 3283

In this position, you measure a temperature via a Pt 100 or Pt 1000 sensor.

Range	Measuring current	Resolution	Accuracy	Protection
- 125°C to + 75°C	< 0.8 mA (Pt 100) < 0.5 mA (Pt 1000)	0.1%0 - 201/	\pm 0.5°C	1000 Vrms
- 200°C to + 800°C	< 0.8 mA (Pt 100) < 0.5 mA (Pt 1000)	0.1 C = 2µV	0,1 % ± 1°C 0,07 % ± 1°C	

"Active" protection by CTP thermistor

Display in ° C (Celsius) / K (Kelvin) / ° F (Fahrenheit) possible

In Temperature measurement, it is possible to modify the scale of the graphic window with the keys **III**. The selected scale is recalled in the help line **i**.

Temperature	In this position, you measure the tempe	erature via a thermocouple:
measurement with thermocouple J or K	Thermocouple K Thermocouple J Internal measurement accuracy	from -40° C to +1200° C from -40° C to +750° C ± 3° C ± 0.1% range (-10° C to 55° C)
MTX 3281 MTX 3282 MTX 3283	Reference temp. accuracy Type of thermocouple The multimeter needs 60' to adapt to th	± 3° C / typical value J and K ne ambient temperature.
dBm measurement (power decibels) MTX 3283	Display of measurement in dBm in relative $(\mathbf{dBm REF})$ adjustable from 1 Ω to 10,0 Resolution Absolute error in dB Additional calculation error Measuring range Protection	ation to a resistance reference 000 Ω, factory set at 600 Ω. 0.01 dB 0.09 x VAC relative error expressed in % 0.01 dB 10 mV to 1000 V 1000 Vrms
dB measurement (voltage decibels) MTX 3283	Display of measurement in dB with the the mode as voltage reference. Resolution Absolute error in dB Additional calculation error Measuring range Protection	 value measured (V ref) at activation of 0.01 dB 0.09 x VAC relative error expressed in % 0.01 dB 10 mV to 1000 V 1000 Vrms

Peak measurement	Secondary values	Peak ranges	Additional error	Protection	
PK+	Peak V t > 250 µs	100 mV to 1000 V	3% ± 50D	1000 Vrms	
PK-	Peak A t > 250 µs	1000 µA to 20 A	4% ± 50D	or 10 Arms	
MTX 3281 MTX 3282 MTX 3283	Specifications valid The value of the pea Additional error for 2 Measurement zero	from 20 % of the rai ak factor results fron 250 μs < t < 500 μs reset : by pressing	nge in A, 10 % of the n calculation: (Pk+ - F : 3 % g the key .	range in V Pk-) / 2 x Vrms	
SURV Function (MIN, MAX, AVG)	Accuracy and rate: i MTX 3281, MTX 3	d. specifications Vo 282, MTX 3283	It and Ampere measu	irements	
Resistive power W	Display of measurer (W REF) adjustable The function perform Ranges Resolution Accuracy Protection	nent in relative pow from 1 to 10,000 Ω ned is: (measure (measure DC and A 100 μW 2 x accur 1000 Vrn	er in relation to a resi , factory-adjusted to 5 ed voltage) ² / W REF ed current) ² * W REF AC racy in VDC or VAC (i ns	stance reference 50 Ω. (unit W) (unit W) in %)	
Power calculation V x A MTX 3282 MTX 3283	In AC and AC+DC voltage measurement : this calculation is limited to 400 Hz The current measurement is always performed in AC+DC. Accuracy (typical) : V measurement accuracy + Peak A measurement accuracy The connection on the COM input must be short and of large diameter, in order				
	to limit the voltage	e drop which influer	nces Volt measureme	nt.	
Duty ratio	Display of the meas	urement in % of a lo	ogic signal (T <u>TL, C</u> MC	DS)	
DC+	DC+ Duty ratio		$= \theta$ $$		
	DC- Duty ratio		= T - θ μ − T	` 	
MTX 3281	Resolution		0.01%		
MTX 3282	Minimum duration fo	or T	10 μS		
MTX 3283	Minimum duration for	or T	200 us		
	Nominal range		5 to 90% typical		
	Sensitivity (10 V ran	ge)	> 30% of the Freq ra	nge < 1 kHz	
	Absolute error on th	e dutv	> 50% of the Freq ra	nge > 1 kHz	
	ratio, expressed in a	ibsolute %	0.05% + 0.0001 / T 0.1% + 0.0005 / T [t i	[t in s] Freq < 1 kH in s] Freq > 1 kHz	
	Additional absolute (slope at switching t	error o zero)	0.1 x C/P C = range in V or in A (for range 1000 V, C	4 = 5000)	
	Protection		P = slope in V/s, A/s 1000 Vrms		
Pulse counting	Dependina on triage	ering conditions of fr	equency meter		
CNT+ _	Minimum pulse dura	ition	5 µs		
CNT	Counting up to		99999		
	Triggering threshold		10 % of range excep	t range 1000 VAC	
MTX 3282 MTX 3283	This threshold is:		positive in \square , negative	ve in Ъ	
	Counter reset to zer	0	by pressing the key	₩.	
and the second sec	For negative events, reverse the cables.				

Pulse width PW+ PW MTX 3282 MTX 3283	Depending on triggering Resolution Minimum pulse width Accuracy Maximum period duration Triggering threshold	conditions of frequency meter. 10 μ s 100 μ s 0.05% \pm 10 μ s 12.5 s 20 % of range except range 1000 VAC		
கு	This threshold is positive in \square , negative in \square . Additional error on measurement caused by slope when crossing zero: see §. Measurement of duty ratio.			
Clock	MTX 3281 Relative time with reset to zero at each powering up MTX 3282, MTX 3283 Real-time clock Accuracy ≈ 30 s / month: real-time clock deviation Display date - month - year / hour - minute - second			
Influences	 Specifications of the accuracy in the field of utilization: Typical specifications = SPEC (1 + 0,05 Δ t ° C) Specification of the considered measurement. Values given p. 33 to 38. Δ T: difference between ambient temperature and input terminal nearest the field of reference. Example : temperature : 38° C DC measurement : 0,02 % + 8 D Δ t ° C = 38 - 28 = 10° C SPEC (38° C) = (0,02 % + 8 D) (1 + 0,05 * 10) = 0,03 % + 12 D Electric field under 3 V/m : 1 per thousand at full scale. This influence does not depend on the temperature. 			
Multimeter Traceability	TRACEABILITY Model No. : 3283 Serial No. : 1001 Firmware Vers. : 1001 Hardware Vers. : C CALIBRATION Last Cal. : 27/11/2005 10:08 Next Cal. : 27/11/2006	 In the « General settings », the menu Traceability opens a file with multimeter up-datings : Model Serial No Firmware Version Hardware Version 		

Calibration A periodic calibration (once a year) of the multimeter is necessary to guarantee the given specification (refer to §. Maintenance, Metrological verification)

General characteristics

Environmental	Altitude	< 2000 m	
Conditions	Reference temperature	23° C ± 5° C	
	Utilization temperature	0° C to 55° C	
	Influence of temperature	see §. Influence	
	Relative humidity	80 % max. for temperatures up to 31° C decreasing linearly to 50 % at 40° C limited to 70 % for 50 MΩ range	
	Sealing	IP 51	
	Operating range	- 10° C to 55° C	
	Storage range	- 40° C to 70° C	
	Battery charge range	0 to 40° C	
Power supply			
MTX 3281	2 possibilities:		
	Batteries	3 x 1.5 V alkaline LR6-AM3 AA	
	 Accumulators 	3 x 1.2 V (*) Ni-MH 2400 mAh AA	
MTV 2000	3 possibilities:		
WITX 3282	Batteries	3 x 1.5 V alkaline LR6-AM3 AA	
MTX 5205	 Accumulators Wall Plug power unit: 	3 X 1.2 V () NI-WH 2400 MAN AA	
	Mains voltage	100 V ± 10% or 240 V ± 10%	
	Frequency	0.3A 50-60 Hz ± 3%	
	(*) Other capacities are possible Via the wall plug, the accumulat from the multimeter.	e. tors can be recharged without removing them	
	Average charging period: 7h30	(with 2400 mAh accumulators)	
Endurance	• with batteries	80 h (VDC mode)	
	• with 2200 mAh accumulators	approximately 65 h (VDC mode)	
	In case of intermittent use of the recommended: this type of cell 3 months of non-use.	e multimeter, powering by Ni-MH cells is not has an self-discharge rate of 100 % after	
ø	Endurances are reduced if the communications interface is a	e LCD backlight and/or the Bluetooth used."	
Display	Graphic LCD	useful part 58 x 58 mm	
		orientable, LED backlit, transflective improvement of contrast in full light	
	Main display	100,000 points + sign + curve adaptive units + bargraph (40 segments) indicators of modes engaged battery level indicator, dangerous voltage indicator	

secondary functions with adapted units

Secondary display

General characteristics (cont'd)

Sefety					
Salety	As per EN 61010-1 :				
	 Insulation 	class 2			
	 Degree of pollution 	2			
	Utilisation	interior			
	Altitude	< 2000 m			
	 Measurement category of "measurement" inputs 	CAT III, 1000 V in relation to earth			
	 Measurement category of "measurement" inputs 	" CAT IV, 600 V in relation to earth			
EMC	 This device was designed i compatibility was tested in Emission (cl. A) and Imm Max. influence in present of radiated fields 	n accordance with EMC standards in force and its accordance with the following standards: nunity EN 61326-1 ce See §. Influences			
US version	Acc. to	UL 61010-1, CSA C22.2 nr. 61010-1 Homologation UL E 309119			
RS232-DB9F or USB optical cables	The optical interface ensures insulation in relation to the connected peripheral (PC) for the transfer of data or for remote control of the multimeter.				
(options)	RS232 communication interface parameters:				
	Transmission speed: 9600 / 19 200 / 38 400 Bauds/s				
	The other transmission parameters are set (8 data bits, 1 stop bit, no parity).				
	USB communication interface: delivered with installation software.				
Bluetooth	Transmission speed	38.4 kbit/s			
(-BT version only)	Sensitivity	-90 dBm			
	Max. power	20 dBm (100 mW)			
	Max. distance	ca. 100 m			
	Battery life	ca. 40 h (VDC mode) with alkaline batteries			
Mechanical cha	aracteristics				
Casing	- Dimonsions 87	$8 \times 265 5 \times 107 5$ in mm (open position)			

Casing	• Dimensions	87.8 x 265.5 x 107.5 in mm (open position) 87.8 x 187 x 48.6 in mm (casing closed)
	Weight	0.450 kg approximately
	Materials	ABS VO (auto-extinguishing) and PC VO external protective moulding in thermoplastic rubber : SEBS
	Sealing	IP 51
Packaging	• Dimensions	
	MTX 3281	240 (L) x 158 (W) x 65 (H) in mm
	MTX 3282, MTX 328	33 297 (L) x 158 (W) x 60 (H) in mm

Supply

Supply

	-						
Delivered with the instrument							
MTX 3281	 Quick Check Guide (bilingual Fr - En) Set of 3 batteries 1.5 V alkaline LR6-AM3 Set of PVC test leads - 4 mm safety touch prods 						
MTX 3282	• • • •	 Quick Check Guide (bilingual Fr - En) Set of 3 accumulators 1.2 V Ni-MH 2400 mAh Wall Plug power/charger unit Set of silicon test leads - 4 mm safety touch prods 					
MTX 3283	• • •						
Supplement delivered with versions MTX 328I-COM MTX 3282-COM MTX 3283-COM	•	Acquisition software kit: - "Data Viewer" Acquisition software for PC - RS232-DB9F Optical cable					
Optional	•	 Calibration software of the MTX 328x range 			HX0059		
Accessories	•	Acquisition software kit: - "Data Viewer" Acquisition software - RS232-DB9F Optical cable				HX0050	
	٠	External ch	arger for NiMH	cells		HX0053	
	٠	USB Optica	al cable + install	ation software		HX0056-Z	
	•	Adapter +	K thermocouple			P06239306	
	•						
		MN 08 or 09	0.5 to 240 AAC	ratio 1000 /1	40 HZ to 10 KHZ	P01120401 or 02	
		Ampflex	0.5 to 2000 AAC	1 mV/A	10 Hz to 20 kHz	P01120504	
		MN 73	0.01 to 240 AAC	1mA/mV or 1A/10mV	40 Hz to 10 kHz	P01120421	
		K2	0.1 to 450 mADC	1 mA/10 mV	DC - 1.5 kHz	P01120074	
		EON	AAC/DC	T A/T V OF T A/TU MV	DC - 8 KHZ	P01120040A	
		PAC21	0.2 to 1400 AAC/DC	1 A/10 mV or 1 A/1 mV	DC - 10 kHz	P01120069	
		"O la su da fa					
	•	2 nanus in		I			
	 Set of 3 1.2 V Ni-MH cells PC Adapter USB/RS232 PC Adapter USB/RLUETOOTH 						
						D01637301	
	USB ontical cable						
	•	Temperatu	re sensor Pt 100	00		HA1263	
Spare parts	•	Fuse 1000	V, 11 A, 10 x 38	mm, 20 kA		541171	
-	٠	Wall Plug p	ower unit EU/US	6		X03205	
	Set of test l	eads - safety tou	ads - safety touch prods				
	•	Optical cable RS232-DB9F				X02736	

Index					
888888 (function)	9	display	9, 42		
Α		duty ratio	39		
absolute deviation	19	-			
AC voltage	33	E			
AC, AC+DC	7	EMC	42		
Accessories	3, 43	endurance	41		
accumulators	10-13, 43	energy	11, 12		
activation (powered)	6, 10	English (Choice of language)	14		
alert	5, 9	environment	3, 41		
amount measured	29, 30	erase	24		
Ampere (function)	5, 13				
audio warning	5, 14, 18	F			
auto (mode)	18	favourite function	29, 30		
auto hold (mode)	8, 18	filter	15		
auto peak (mode)	8, 18	French (Choice of language)	14		
automatic detection	4	FREQ	22, 25		
automatic recording	8, 29	frequency measurement	36		
automatic stop	14	main functions	7, 17		
AVG	20	secondary functions	9, 25		
		fuse	4, 5, 13 ,43		
В					
back-lighting	8, 9, 15	G			
bargraph	9	General (function)	11		
basic (mode)	15	General (menu)	12, 14		
batteries	10	general settings	11, 31, 40		
Bluetooth	5, 31, 32, 42	Graphical display	9		
buzzer	4, 5, 10, 14	guarantee	4		
0					
C apple connection	21	H	7 0 04 00		
	5 7 0 17 20	neip (I)	7, 9, 31, 32		
	3, 7, 9, 17, 30	HOLD (mode)	8, 18		
	33, 35, 30 42	numidity	3, 41		
casing	42				
	25 30	I-J-K	0.45		
coof A coof R	25, 58		8, 15		
	27,20,29 5 17 19	innual settings	14		
comm	3, 17, 10		9		
communications	5		31 7		
configuration	J 7 8 15 18	J (Inermocouple)	/ 6 10		
configuration (menu)	15 18		0, 12		
continuity measurement	17	K (inernocoupie)	1 6		
continuity mede	37	keyboards	0		
current measurement	7 16 34	Keys	7,0		
current measurement	7, 10, 34				
D		LCD contrast	8 9 14 41		
- date	14, 20		0, 0, 14, 41		
dB measurement	38	М			
db9f	31, 42, 43	main display	19 41		
dBm REF	15	main functions	7 16 17 24		
dBm	38	main measurement	18-21		
DC voltage	33, 34	maintenance	4		
DC	25, 34, 39	MANU (kev)	8, 18, 29		
diode measurement	17, 37	MATH (function)	25-30		
		· · · · · /	-		

Index

MAX measurement category MEM (function) MEM (key) MEM (mode) memory MIN monitoring N - O NO HOLD (mode)	20, 21, 24 3 9, 23, 24 8 5, 8, 14, 21, 22 24 20, 21, 24 29 8, 18, 29	temperature measurement terminal board thermocouple time traceability transient overvoltages type of energy U - V - W unit Wall plug	7, 8, 17, 18, 38 6 7, 17 13, 14, 20 40 5 11 26, 27, 28 12, 13
optical cable optical link	31, 42, 43 5		
Р			
parameters peak factor peak measurement PER (period) Pk (peak) power supply power unit (Wall plug) protection Pt100 (sensor) Pt1000 (sensor) pulse counting pulse width	30 18, 25 39 25 25 12, 14, 41 10, 37, 41, 43 3, 5, 13 7 7 39 40		
R			
range recharge (charge) recorded data recording REL resistance measurement resistive power RS 232	18 10-13 20, 23 20-24, 29, 30 8, 9, 17, 18 7, 17, 37 16, 25, 26, 39 5, 9, 31, 42, 43		
S			
safety secondary displays secondary functions sensor software kit SPEC (function) standby supply SURV SX-DMM	3, 4, 10, 42 8, 9 9, 23, 25, 36 17, 38, 43 31 21 14 43 5, 8, 9, 14, 20 31, 32		
T TC J (thermocouple) TC K (thermocouple) temperature	7, 17 7, 17 3, 11, 33, 35, 40		